

**ISSC M22 M111000 22 LR, \$400
GUN TESTS GRADE: B-**

We liked the full-size faux-Glock feel, and its training-gun concept. The M22 handled and shot like an 'A'-rated gun when paired with CCI ammo, but it had multiple malfunctions with all other test ammunition. A slide-release issue and a uncomfortable ribbed trigger also cost it points.

SPECIFICATIONS

OVERALL LENGTH	7.0 IN.
BARREL LENGTH	4.0 IN.
SIGHT RADIUS	5.5 IN.
OVERALL HEIGHT	4.8 IN.
FRONT STRAP HEIGHT	2 IN.
BACK STRAP HEIGHT	2.8 IN.
WEIGHT UNLOADED	21.4 OZ.
CAPACITY	10+1
MAXIMUM WIDTH	1.0 IN.
GRIP THICKNESS (MAX)	1.3 IN.
GRIP CIRCUMFERENCE (MAX)	5.3 IN.
FRAME	BLACK POLYMER
BARREL	STEEL
SLIDE	BLUED ALUMINUM
GRIP	TEXTURED POLYMER
TRIGGER PULL WEIGHT SINGLE ACTION	4.9 LBS.
TRIGGER SPAN SINGLE ACTION	3.4 IN.
WARRANTY	1 YEAR
U.S. DISTRIBUTOR	AUSTRIAN SPORTING ARMS
TELEPHONE	(800) 967-3940
WEBSITE	WWW.AUSTRIANSPORTINGARMS.COM



Right: The ISSC's ambidextrous decocking levers worked, but were a little awkward to operate.

Right: Sights consisted of a white rectangle on the front, with an adjustable rear sight that was framed with a squared-off white line (shown). The sight picture was easy to access and was judged the best out of our trio of contestants.



Above: The M22 internals are fairly standard, with the exception of a recoil spring, which surrounds the barrel of the gun, rather than using a guide rod. Disassembling the M22 was Glock-like. The two latching levers are depressed while tugging the slide slightly rearward, retracting the slide fully to the rear while lifting it upward, and then sliding it forward off the frame. The ISSC had problems with non-CCI ammunition, often failing to fully return to battery.