
## REMINGTON M887 NITROMAG NO. 82500 3½-INCH 12 GAUGE, \$399

## GUN TESTS GRADE: D

The Remington M887 fails on handling, finish, overall build quality, and function. It did not perform adequately at all.

|                                |                    | IMPRICION AND COMPANY INC. INC. NO. |                     |                   |
|--------------------------------|--------------------|-------------------------------------|---------------------|-------------------|
|                                | Drop @ Heel        |                                     |                     |                   |
| SPECIFICATIONS                 | Buttplate          | Rubber recoil pad                   | Stock               | Black plastic     |
| Overall Length                 | Weight Unloaded    | 7.25 LBS.                           | Grip Type           | Pistol grip       |
| Barrel Length                  | Magazine Type      | Tube                                | Сноке               | M, FLUSH-MOUNT    |
| SIGHTPLASTIC GREEN TUBE FRONT, | Magazine Capacity  | 4                                   | Trigger Pull Weight | 4.6 LBS.          |
| PLASTIC RED CENTER BEAD        | STEEL SHOT CAPABLE | YES                                 | Warranty            | 2 year limited    |
| LOP                            | Safety             | Crossbolt                           | Telephone           | (301) 283-6981    |
| Drop @ Comb                    | Action             | BLACK PLASTIC                       | Website             | WWW.RFMINGTON.COM |

Right: As rough as we discovered the machining of the barrel to be, its mating surface inside the receiver was just as bad. Left: It is apparent from inspecting the inside of the receiver that most of this "steel receiver" is not metal at all—instead, it's thick plastic with visible mold





lines and plastic flashing pieces hanging off.